Easy Spread Exterior Latex Flat House Paint

DESCRIPTION

A flat house paint formulated to provide a quality finish for your exterior house & trim.

FEATURES

- Applies easily
- Tools rinse clean in soapy water
- For wood and masonry
- Dries to a flat finish

VOC / MIR (sprays)
100 gm/l
(0.83 lbs/gal)

NET WEIGHT
10.2 lbs/gal

AVAILABLE SIZES
5-gallon, 2-gallon, gallon

SHIPPING WT
5-gal pail/53 lbs
2-gal pail/22 lbs
4-gal case/43 lbs

AVAILABLE COLORS

8-2000 White, 8-2029 Cape Cod Gray, 8-2031 Bark Brown, 8-2039 Stucco, 8-2041 Barn Red

SHIPPING RESTRICTION
CA

PRODUCT STATISTICS

DRYTIME-TOUCH	DRYTIME-RECOAT	WET/ FILM THK	FILM THK /DRY:	FINISH	GLOSS
1 hour	8 hours	5.0 mils	1.0 mils	Flat	< 5 @ 60°

FLASHPOINT	COVERAGE	VISCOSITY	VEHICLE	SOLVENT
> 200° F	Up to 300 sq ft/gal	92 - 98 KU	Vinyl Acrylic Latex	Water

SURFACE PREP

Previously Painted Wood: Scrape to remove loose, peeling paint and sand smooth. Remove all loose dirt and chalk. Scrub protected areas under eaves to remove invisible deposits which cause peeling. Remove any mildew using one quart of household bleach in three quarts of water. Rinse thoroughly. Wear goggles and gloves to prevent contact with the bleach. Sand any glossy areas to dull the surface. Caulk cracks and putty nail holes. Spot prime any bare areas with oil base exterior primer. Previously Painted Masonry: Remove loose or powdery paint and chalk. Spot prime bare areas with this product. Metal Surfaces: Scrape or wire brush to remove rust and loose paint. Spot prime bare metal with the proper metal primer. New Unpainted Surfaces: Wood Siding & Trim: Caulk cracks and joints, putty nail holes. Prime with an alkyd or acrylic latex exterior primer. Masonry: Newly poured concrete must be weathered a minimum of 90 days. Concrete block should be given two coats of Easy Spread Exterior Latex Flat House Paint. Galvanized Metal Check for stabilizing film, remove appropriately and prime with latex galvanized primer. Ferrous Metal: Prime with a red oxide rust inhibiting primer. Bare Aluminum: Prime with an acrylic latex primer.

APPLICATION

Stir thoroughly. Apply generously with nylon or polyester brush or good quality roller. Stop painting at least four hours before nightfall, stopping at the end of a wall or corner. Do not paint when temperatures are below 50° F, in direct sunlight, or before rain is expected within 24 hours. On hot days, surface may be dampened with water to slow drying. DO NOT THIN.

WARNING

If you scrape, sand or remove old paint, you may release lead dust. LEAD IS TOXIC. EXPOSURE TO LEAD DUST CAN CAUSE SERIOUS ILLNESS, SUCH AS BRAIN DAMAGE, ESPECIALLY IN CHILDREN. PREGNANT WOMEN SHOULD ALSO AVOID EXPOSURE. Wear a NIOSH approved respirator to control lead exposure. Clean up carefully with a HEPA vacuum and wet mop. Before you start, find out how to protect yourself and your family by contacting the National Lead Information Hotline at 1-800-424-LEAD or log on to www.epa.gov/lead.

Yenkin-Majestic Paint Corp. 1920 Leonard Ave. Columbus, OH 43219 Ph: (800) 848-1898 Fx: (614) 258-3062

REVISED DATE   4/3/2014